

Safety Alert

Number: 20-18

Published: 01/11/2023

Subject: Dropped Lightning Rod

What Happened / Narrative

A lighting rod conductor mounted on top of a dynamic gangway tower for a Walk-to-Walk vessel was found lying on the deck below the tower. No personnel onboard the vessel observed or heard the object fall.

The potential for serious injury existed due to:

- the location of the dropped area (deck is frequented by personnel)
- the weight of the object (1.5kg)
- the distance it fell (26m)

Why Did it Happen / Cause

There was no obvious damage to the rod or fittings, it is assumed that the fittings loosened / unscrewed over time.

The incident presents immediate causes such as:

- Impact of rough or bad weather on the rod securing connections
- lack of inspection/maintenance on the securing of the rod
- Design deficiency in terms of a secondary securing mechanism for the rod



Corrective Actions Taken / Recommendations

- Create a planned maintenance schedule to regularly check the lighting rod conductor fittings.
- This planned maintenance schedule must be applied to other installed equipment i.e., lights, cameras, wind sensors etc.
- Install a secondary securing mechanism to the lighting rod components and other equipment where necessary.

The information contained within this Safety Alert and the associated MSF web site is provided in good faith for the benefit of our members and does not constitute and is not intended to constitute professional advice or any form of formal representation on behalf of any MSF member or officer. The text as provided by submitting organisations may be amended to ensure that it is brief, informative and readable but will as far as reasonably practicable remain as per the intent of the original submission. For the avoidance of doubt, no liability whatsoever shall be attached to any guidance, recommendation or statement contained therein. Contents should be reviewed individually by recipients who will determine relevance to their own operations.

Safety Alert

Photographs / Supporting Information



The information contained within this Safety Alert and the associated MSF web site is provided in good faith for the benefit of our members and does not constitute and is not intended to constitute professional advice or any form of formal representation on behalf of any MSF member or officer. The text as provided by submitting organisations may be amended to ensure that it is brief, informative and readable but will as far as reasonably practicable remain as per the intent of the original submission. For the avoidance of doubt, no liability whatsoever shall be attached to any guidance, recommendation or statement contained therein. Contents should be reviewed individually by recipients who will determine relevance to their own operations.