

# **Safety Alert**

Number: 18-07 Published: 22/02/2018

Subject: AB Lifted by Crane – High Potential Near Miss

### What Happened / Narrative

A routine operation was being carried out to transfer a bulk hose between a platform and a PSV, with the help of the platform crane.

As the hose was landed on the vessel deck, one of the AB's went to release the hook from the lifting sling. While slightly bending forward and down to clear the hook, the crotch strap on the AB's lifejacket formed a larger than normal bight. As the AB released the hook it was incorrectly placed inside the bight and as he returned to the upright position the hook was caught. Unfortunately, the AB did not notice this, and then subsequently signalled to the crane operator to "hoist". This resulted in the AB being lifted above the deck and out over the side of the vessel. The AB's immediate reaction was to hold onto the pennant wire to keep tension off the crotch strap. The crane driver and second AB quickly became aware of the situation and were able to land the AB safely back on deck. The duration of the incident was in the region of 11 seconds from the AB being lifted and returned to deck.

## Why Did it Happen / Cause

- The crotch strap on the lifejacket was not suitably tightened on this occasion. A change in body posture created a larger than normal "bight" which allowed the hook to be attached.
- The hook and lifting sling landing directly on the deck of the vessel.
- AB's posture during the disconnection of hook.
- A momentary lack of awareness on the actual location of the hook, i.e. left open, close to the body, the signal to hoist.

### **Corrective Actions Taken / Recommendations**

Fortunately, there was no personal injury sustained during this incident. However, there was a high potential. Similar incidents have occurred in the industry.

- Hook awareness ensure hook is clear of the body and any snagging hazards.
- Buddy check during the toolbox talk prior to task commencement.
- Raise awareness across fleet for all lifting operations.
- Discuss with Industry and fleet deck crews on a suitable "pause point" prior to giving signal to crane operator.

# **Photographs / Supporting Information**



The information contained within this Safety Alert and the associated MSF web site is provided in good faith for the benefit of our members and does not constitute and is not intended to constitute professional advice or any form of formal representation on behalf of any MSF member or officer. The text as provided by submitting organisations may be amended to ensure that it is brief, informative and readable but will as far as reasonably practicable remain as per the intent of the original submission. For the avoidance of doubt, no liability whatsoever shall be attached to any guidance, recommendation or statement contained therein. Contents should be reviewed individually by recipients who will determine relevance to their own operations.